





1



x 2
R1-61381

2



x 2
C1-09100

3



x 2
C1-09105

4




x 4
K3-06403
Ø6 x 40 - Torx 30

5




x 2
K3-06013
Ø4 x 20

6




x 2
H1-69300

7



x 1

11



x 1
R1-66005


1008020

12




x 4
Ø4 x 25

13



x 1




Ø6 x 80





PH
Torx 30




16mm







Ø6mm







2




3






4a







5




6






7




8



9




➔ 10



➔ 11

10



11

